

TransitCheck®

Electronic Pre-Trip Inspection Solution
works with
Pre-Trip Module

Overview

- Automated inspections using app and web data system by Revecorp
- Automates maintenance and tracks vehicle and driver performance
- Takes the driver through a step-by-step inspection process
- Works with InterMotive's Pre-Trip Module to make the inspection a one-person job

Features

- Eliminates paper and saves costs
- Ensures a completed inspection by tracking inspection duration and distance
- Generates maintenance failures with photos
- Use with Pre-Trip Module to monitor fuel use, mileage, speed, idle time, diagnostic trouble codes and more
- Automatically captures VIN and mileage when used with Pre-Trip Module
- Customize desired inspection inputs

Sample Reports

Sample Company
12001 Hobble Drive, Middleton, CA
95602 ph: (530) 867-5309

PASS

Sample Company
12001 Hobble Drive, Middleton, CA 95602
ph: (530) 867-5309

WARN

PRE TRIP INSPECT

Inspector: **Rashawn Watson**
ID: **431**
Mileage: **1234**
Fuel Level: **4.5 gal(c), 6%(u)**
MIL On?: **N/A**

Sample Company
12001 Hobble Dr., Middleton, CA 95602
ph: (530) 867-5309

FAIL

PRE TRIP INSPECT

Inspector: **Joseph McCaffey**
ID: **221**
Mileage: **1254**
Fuel Level: **56.3 gal(c), 75%(u)**
MIL On?: **N/A**

Inspection Date: **09-MAR-2017 10:45 AM** Report ID: **4421** Inspection Type: **PRE TRIP INSPECT**

2015 FORD Other Unlisted

Insp Template: **4421-PRETRIP**

Inspected By: **Gwen Jacobs**

Plate: **VA-**

Insp Tmpl Ver: **04-FEB-2017**

Staff ID: **411**

VIN: **1FDFE4FS9HDC06719**

Insp Begin: **09-MAR-2017 10:33 AM**

Odometer: **4557**

Asset: **ASSET6719**

Insp End: **09-MAR-2017 10:45 AM**

Fuel Level: **56.3 gal(c), 75%(u)**

Route: **NOROUTE**

Elapsed: **11 min / 211.2 ft**

MIL On?: **N/A**

Passing Items

- | | | |
|---|--|---|
| + INTERIOR:Interior Cleanliness | + INTERIOR:Wheel Chair Tie Downs | + INTERIOR:Step Well Lights |
| + RTFRONT:Tire Pressure, Tread, Condition | + RTFRONT:Passenger Door | + UNDERHOOD:Engine Oil |
| + UNDERHOOD:Radiator Fluid | + UNDERHOOD:Underhood Leaks | + FRONT:Headlights High Beam |
| + FRONT:Turn Signals | + FRONT:Headlights Low Beam | + LTFRONT:Tire Pressure, Tread, Condition |
| + LEFT:Vehicle Body Damage | + LTREAR:Tire Pressure, Tread, Condition | + REAR:Backup Lights and Alarm |
| + REAR:Turn Signals | + REAR:Brake Lights | + RIGHT:Wheel Chair Lift Leakage |
| + RIGHT:Wheel Chair Lift Cycle | + RIGHT:Wheel Chair Lift Lights | + RTREAR:Tire Pressure, Tread, Condition |
| + INTERIOR:Windshield | + RIGHT:Vehicle Body Damage | + DASH:Odometer Reading |

Warning Items

no warning items noted

Failing Items

x INTERIOR:OSHA Kit

Note: **KIT MISSING**

Driver Certification

Gwen Jacobs certifies that she has performed the PRE TRIP INSPECTION inspection for this Vehicle (VIN: 1FDFE4FS9HDC06719) and that the results indicated above for this Inspection (ID: 4421) are true and correct.




Signature Timestamp: **09-MAR-2017 07:45 AM**

PRE TRIP INSPECT
Inspector: **Joseph McCaffey**
ID: **221**
Mileage: **1254**
Fuel Level: **56.3 gal(c), 75%(u)**
MIL On?: **N/A**

Well Lights
Engine Oil
Left High Beam
Pressure, Tread, Condition
Lights and Alarm
Air Lift Leakage
Pressure, Tread, Condition
Reading

Wheel Chair Tie Downs
Pressure, Tread, Condition
Underhood Leaks
Turn Signals
Pressure, Tread, Condition
Turn Signals
Air Lift Lights
Windshield


11:08 AM

09:39 AM

